

W/O split

|                        |              |             |
|------------------------|--------------|-------------|
| DART AEROSPACE LTD     | Work Order:  | 21620A      |
| Description: Head Rest | Part Number: | D3303-041   |
| Dwg: D3303 Rev. A      | Qty:         | 40          |
|                        |              | Page 1 of 1 |

| Step | Location              | Procedure  | By             | Date        | Qty         |       |   |           |                  |         |             |          |      |        |     |                       |          |        |             |          |   |
|------|-----------------------|--|----------------|-------------|-------------|-------|---|-----------|------------------|---------|-------------|----------|------|--------|-----|-----------------------|----------|--------|-------------|----------|---|
| 1    | DC                    | Issue Traveler   | [Signature]    | 04.09.29    | 40          |       |   |           |                  |         |             |          |      |        |     |                       |          |        |             |          |   |
| 2    | GA                    | Bond foam to D3303-043 bracket assembly as per Dwg D3303 using 3M 1300/1300L or 8046 adhesive<br>Pick:<br><table><tr><th>Qty</th><th>Part Number</th><th>Description</th><th>Batch</th></tr><tr><td>1</td><td>D3303-043</td><td>Bracket Assembly</td><td>B21624A</td></tr><tr><td>1</td><td>D3305-1</td><td>Foam</td><td>B21626</td></tr><tr><td>A/R</td><td>3M 1300/1300L or 8046</td><td>Adhesive</td><td>A15604</td></tr></table> Identify as D3303-041 | Qty            | Part Number | Description | Batch | 1 | D3303-043 | Bracket Assembly | B21624A | 1           | D3305-1  | Foam | B21626 | A/R | 3M 1300/1300L or 8046 | Adhesive | A15604 | [Signature] | 04.10.21 | 4 |
| Qty  | Part Number           | Description  | Batch          |             |             |       |   |           |                  |         |             |          |      |        |     |                       |          |        |             |          |   |
| 1    | D3303-043             | Bracket Assembly   | B21624A        |             |             |       |   |           |                  |         |             |          |      |        |     |                       |          |        |             |          |   |
| 1    | D3305-1               | Foam   | B21626         |             |             |       |   |           |                  |         |             |          |      |        |     |                       |          |        |             |          |   |
| A/R  | 3M 1300/1300L or 8046 | Adhesive   | A15604         |             |             |       |   |           |                  |         |             |          |      |        |     |                       |          |        |             |          |   |
| 3    | GA                    | Cover Head Rest with D3306-041 as per Dwg D3303<br>Pick:<br><table><tr><th>Qty</th><th>Part Number</th><th>Description</th><th>Batch</th></tr><tr><td>1</td><td>D3306-041</td><td>Cover Assembly</td><td>B21627</td></tr></table>  | Qty            | Part Number | Description | Batch | 1 | D3306-041 | Cover Assembly   | B21627  | [Signature] | 04.10.21 | 4    |        |     |                       |          |        |             |          |   |
| Qty  | Part Number           | Description  | Batch          |             |             |       |   |           |                  |         |             |          |      |        |     |                       |          |        |             |          |   |
| 1    | D3306-041             | Cover Assembly   | B21627         |             |             |       |   |           |                  |         |             |          |      |        |     |                       |          |        |             |          |   |
| 4    | QC5                   | Inspect work to Step 3   | [Signature]    | 04.10.22    | 4           |       |   |           |                  |         |             |          |      |        |     |                       |          |        |             |          |   |
| 5    | ST                    | Identify parts with batch number and part number using a fine point permanent marker as per Dwg D3304 and Stock  | Done at Bagley |             |             |       |   |           |                  |         |             |          |      |        |     |                       |          |        |             |          |   |
| 6    | AC                    | Cost / part: 107.91  | Sys            | 04.10.25    | 4           |       |   |           |                  |         |             |          |      |        |     |                       |          |        |             |          |   |
| 7    | DC                    | Close W/O 107.91<br>Inspect Level 21   | [Signature]    | 04.10.26    | 4           |       |   |           |                  |         |             |          |      |        |     |                       |          |        |             |          |   |

| Rev | Date     | Change    | Revised By | Approved    |
|-----|----------|-----------|------------|-------------|
| A   | 04.09.07 | New Issue | KJ/JLM     | [Signature] |

RELEASED  
04/04/09-08

# Job Costing Report

Dart Aerospace Ltd.  
Hawkesbury

Sep 29, 2004  
07:44 am

Work Order No : 0021620 **A**  
Project Name : D3303-041  
Project For : WK443  
Work Order Type : Main  
Main WO Number :  
House Part Number : D3303-041  
Description : Head Rest  
Manufactured : Yes  
Amount Req'd : **404**  
Amount Done : 0  
Start Date : 09-28-04  
Est Finish Date : 10-21-04  
Act Finish Date :  
Drawings Req'd : No  
Ok for Approval :  
Approval Rec'd :

Department Code:  
Burden Flags : NNNNNNNN  
WO Status : Open  
Invoice State : Not Invoiced  
Invoice Date :  
Invoice Number :  
Invoice Amount : 0.00  
Order Entry No :  
OE Value : 0.00  
Est Margin : 0.000%  
Actual Margin : 0.000%  
\$0 Posted to Finished Goods

|                     | Estimated | Actual | Var. % | Posted | To Post |
|---------------------|-----------|--------|--------|--------|---------|
| Material Cost :     | 0.00      | 0.00   | 0.00   | 0.00   | 0.00    |
| Engineering Hours : | 0.00      | 0.00   | 0.00   | 0.00   | 0.00    |
| Engineering Cost :  | 0.00      | 0.00   | 0.00   | 0.00   | 0.00    |
| Production Hours :  | 0.00      | 0.00   | 0.00   | 0.00   | 0.00    |
| Production Cost :   | 0.00      | 0.00   | 0.00   | 0.00   | 0.00    |
| Packaging Hours :   | 0.00      | 0.00   | 0.00   | 0.00   | 0.00    |
| Packaging Cost :    | 0.00      | 0.00   | 0.00   | 0.00   | 0.00    |
| OverHead Hours :    | 0.00      | 0.00   | 0.00   | 0.00   | 0.00    |
| OverHead Cost :     | 0.00      | 0.00   | 0.00   | 0.00   | 0.00    |
| CNC Hours :         | 0.00      | 0.00   | 0.00   | 0.00   | 0.00    |
| CNC :               | 0.00      | 0.00   | 0.00   | 0.00   | 0.00    |
| Misc. Hours :       | 0.00      | 0.00   | 0.00   | 0.00   | 0.00    |
| Misc. :             | 0.00      | 0.00   | 0.00   | 0.00   | 0.00    |
| Burden :            | 0.00      | 0.00   | 0.00   |        |         |
| Total Cost :        | 0.00      | 0.00   | 0.00   |        |         |
| Margin :            | 0.000     | 0.000  |        |        |         |
| Selling Cost :      | 0.00      | 0.00   |        |        |         |

|                          |           |        |
|--------------------------|-----------|--------|
|                          | Estimated | Actual |
| Labour Hrs/Amount Done : | 0.00      | 0.00   |
| Profits/(Loss) :         | 0.00      | 0.00   |